



News Release

January 1, 2023

Contact: Jake Reint, Flint Hills Resources (612) 636-6954
Jake.reint@fhr.com

Flint Hills Resources Ingleside Dock 5 Release Statement:

Flint Hill Resources continues to respond to the release of approximately 335 barrels of light crude oil from a pipe failure at its Ingleside crude oil terminal that occurred on December 24.

Ground and aerial patrols continue to identify areas in Corpus Christi Bay that require clean up. Clean up efforts have occurred and/or remain underway at various locations in Corpus Christi Bay, including near Dock 5 at the Flint Hills Resources Ingleside Crude oil terminal, the Ship Channel, North Beach, Indian Point, Nueces Bay, the Rookery Island, and the Dredge Material Placement Area (DMPA10).

Residents are encouraged to report any material or oil sheens they observe to the Flint Hills Resources Ingleside Response Center at 361-396-2831.

Flint Hills Resources continues to work in full cooperation, oversight and coordination with local, state and federal authorities, including the US Coast Guard, Texas General Land Office, and the Port of Corpus Christi Authority, who have all been providing assistance.

More than 3,000 absorbent pads and 60,000 feet of boom have been or are available to be deployed to assist with the recovery efforts and protect sensitive habitat and shoreline.

Flint Hills Resources also continues to work with the Texas Parks and Wildlife Department to respond to reports of impacted wildlife. The Texas Parks and Wildlife Department has confirmed that a total of four birds are believed to have died due to exposure to crude oil since the event occurred on December 24. One turtle also has been treated for potential exposure.

The cause of the December 24th incident is still under investigation. Flint Hills Resources Ingleside Dock 5 remains idled.

The following phone number has been established to receive claims: 1-800-254-1122.

###